

VEHICLE INSPECTION REPORT

KN72YDK

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/10/2022

Year 2022

Mileage 21,619 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9106332P504162

Body Style Panel Van L2

MOT Due 03/11/2026

CAP Clean £20,000.00

CAP Average £18,500.00

CAP Below £15,950.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Qtr Panel nsr
Dented
With Paint Damage



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Bumper Rear Moulding
Broken
Replace



5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage



8: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		