

VEHICLE INSPECTION REPORT

WX17JYZ

Isuzu D-Max 2.5 TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 10/05/2017

Year 2017

Mileage 97,989 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN MPATFS86JFT030438

Body Style Pickup Double Cab

MOT Due 21/01/2027

CAP Clean £6,200.00

CAP Average £5,150.00

CAP Below £3,825.00

Gearbox MANUAL

Gears 6

Axle Combi 4x4

WARNING LIGHT ON DASH REMOTE WINCH, TOW BAR, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR




Spare


Features

- Bluetooth connection
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips



3: Number Plate Front
Broken
Replace

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Chipped
Multiple Chips

8: Panel Rear
Scratched
Over 25mm Thru Paint




9: Panel Rear
Scratched
Over 25mm Thru Paint

10: Qtr Panel osr
Chipped
Multiple Chips




11: Door osf
Chipped
Multiple Chips

12: Wing osf
Scratched
Over 25mm Thru Paint



13: Wing osf
Dented
Over 30mm

14: Seat Base Cover osf
Soiled
Heavy



15: Seat Base Cover nsf
Soiled
Heavy

16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		